DRESS CODE AND CODE OF CONDUCT for Contractors entering the lab, process halls or storage rooms

When entering the lab, process halls or storage rooms, contractors will ALWAYS:



Take off any jewelry, only flat weddings rings are allowed



Never touch anything nor take any pictures/make any video's without explicit consent of the communication manager of BBEPP



Tie medium and long hair together



Wear a hair (and/or beard) net when instructed to do so (only in case food grade processes are running)



Wash and disinfect hands before entering




Respect distances advised by the accompanying BBEPP staff member with respect to any equipment or resources



Cover small wounds on hands or arms with a blue (waterproof and metal detectable) adhesive plaster before (re-)starting the work Contractors performing any operational activity ALWAYS wear:

- Safety glasses
- Safety or working clothes (long sleeves/long pants)
- Safety shoes
- Other extra Personal Protective Equipment (PPE), depending on
 took



Your Contact Person at Bio Base Europe Pilot Plant is:

Mobile Phone Number Contact Person:

Code of conduct for contractor Creation date: 31/07/2023 Version 5



Bio Base Europe

Pilot Plant

for CONTRACTORS

Health, Safety, Quality and Food Safety are key at Bio Base Europe Pilot Plant, therefore we kindly request contractors to always respect our Code of Conduct

GENERAL GUIDELINES FOR CONTRACTORS



Wash and disinfect your hands

- Before entering the lab, process halls or storage rooms
- After each toilet visit
- In case of dirty hands during work
- After lunch/eating




- No eating
- No drinking
- No chewing

allowed outside the meeting rooms, cafeteria and kitchen



Smoking is only allowed outside the main entry (parking 1)



- Everyone is responsible for his/her personal hygiene and safety
- No photography and filming is allowed on site
- You have to register every day upon arrival and deregister at departure
- Please report any sickness or skin infections upon visitor registration
- Report injuries immediately at the reception
- Contractors always ask permission to enter process halls, labs or storage rooms
- Contractors are not allowed to perform any actions in production processes
- You need a work permit for every work you need to do.
- Waste processing
 - BBEPP is not liable for the collection and processing of the contractor's waste.
 - A pick-up can be arranged in dialog with your BBEPP contact.





Welcome at Bio Base Europe Pilot Plant.

For health, safety and quality reasons, please complete the information below*.

Company:
Name:
Mobile Phone Number:
License Plate:
Your Contact Person at Bio Base Europe Pilot Plant i
Start date of your assignment:
End date of your assignment:
Safety welcome given by:
Name:
Date:
Signature: Bio Base Euro Pilot Plant

* please fill in with capital letters.